

HCI Inventory of Pre-Owned Monoplace chamber Systems

ETC Baramed- Chambers for Sale

Latest Update: July 18, 2020 by SDR

Item Number	Model	Inside Diamter	Build Year	Panel Config.	Cycles	10 Year Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB
416-1	Baramed	30"	2000					Original	Now	As-is, No warranty, Warranty on request	\$31,000	NYC
416-2	Baramed	30"	2006	standard	4269	Seal Service in 2016		Original	Now	As-is, No warranty, Warranty on request	\$43,500	NYC
416-3	Baramed	30"	2005	reverse	3630	Seal Service in 2016		Original	Now	As-is, No warranty, Warranty on request	\$41,000	NYC
416-5	Adjustable Height Gurney for Baramed, Including Mattrees & Patient Tray (2 available)								Now	As-is, No warranty		
524-1	Baramed XD (Under Contract)	34"	2007	standard	<5,000	Due	Original	Original	Now	180 day limited warranty (*)	\$29,500	SE US
524-2	Baramed XD (Under Contract)	34"	2007	reverse	<5,000	Due	Original	Original	Now	180 day limited warranty (*)	\$29,500	SE US
532-1	Baramed XD	34"	2008			Due	IPC upgrade	Original	Now	180 day limited warranty (*)	\$32,000	South-central US
532-2	Baramed XD	34"	2008			Due	Orignal (Ampro)	Original	Now	180 day limited warranty (*)	\$29,000	South-central US
532-3	Baramed XD	34"	2009			Due	IPC upgrade	Original	Now	180 day limited warranty (*)	\$35,000	South-central US
532-4	Baramed XD	34"	2010			Due	Orignal (Ampro)	Original	Now	180 day limited warranty (*)	Call	South-central US
541-1	Baramed XD	34"	2010	standard		Due	Ampro. To be upgraded at sale	Original	Now	180 day limited warranty (*)	\$35,000	SE US
541-2	Baramed XD	34"	2011	reverse		Due 2021	Ampro. To be upgraded at sale	Original	Now	180 day limited warranty (*)	\$38,000	SE US
541-3	Baramed XD SELECT	34"	2007	reverse		Due	Panel PC. To be upgraded at sale	Original	Now	180 day limited warranty (*)	\$37,500	SE US
(*) Requires post del'y PM by tech acceptable to HCI. If performed by HCI this is subject to separate pricing. International shipments are "as-is" at time of shipment. Warranties are normally parts only.												

General Notes to ETC Listings:

All chambers come with standard (non hydraulic) gurney unless inidcated otherwise, patient tray and mattress
 All chambers are built to PVHO-1, but not all are National Board stamped (newer ones are)
 Maintenance records are available for most chambers
 All chamber computers either have Windows based computer or have been upgraded as noted
 All prices and technical details subject to change without notice.

Specific Notes:

Sechrist Chambers for Sale

Latest Update: July 18, 2020 by SDR

HCI Inventory of Pre-Owned Monoplace chamber Systems

Item Number	Model	Inside Diamter	Build Year Chamber/ window	Control Panel Config.	Cycles	10 Year Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB
TBD	2500B	25"	Various	std/reverse on request	0	Due in 2028	Pneumatic	New at shipment	14 wks	New window & seals at sale. Well suited for veterinary centers	\$43,000	Mid-Atlantic
469-2	2500B	25"	~1990	Standard	N/A	Out of date window	Pneumatic	Original, Past 20 years	Now	No warranty except working at sale date	\$6,500	SE US
490-1	2500B (Reduced)	25"	1987/2008	Standard	2,851	Due	Pneumatic	New in 2008	Now	Gurney sold separately	\$7,900	SE US
490-2	2500B (Reduced)	25"	1993/2003	Reverse	3,293	Due	Pneumatic	New in 2003	Now	Gurney sold separately	\$6,900	SE US
Notes for above two chambers								Five wheel adjustable height ("hydraulic")			\$3,500	Mid-Atlantic
1. Deduct \$1,000 per chamber if both chambers								Five wheel, fixed height			\$1,900	SE US
2. Gurney options:								Four wheel, chromed-steel frame			\$500	SE US
531	2800 set up for air ventilaiton w/compressor	28"	2001	Standard	6,100	None	Pneumatic	Original	Now	180 day ltd warranty(*)	\$38000 installed most locations	Southern CA
463-1 to 463-4	3200, 3200R	32"	1997/2009	Std or rev.	<50	None	Pneumatic	New at time of purchase		180 day limited warranty (*) (2)	\$55,000	Mid-Atlantic
517-6	3200, 3200R	32" White	2009	Std or rev.	Call	Due	Pneumatic	Original	Now	180 day ltd warranty(*)	\$36,500	Mid-Atlantic
537-1	3200, Blue	32"	1997/2017	Standard	1,744	Due 2019	Pneumatic	New in 2017	Now	180 day limited warranty (*)	Call	US Mid-west
523-1	3300H, Silver	32.5"	2012	Standard	2888	None	Pneumatic	Original	Now	180 day limited warranty (*)	\$48,500	Puerto Rico
522-1	3200, Blue	32"	2008	Standard	~19000	None	Pneumatic	Original	Now	180 day limited warranty (*)	\$34,000	Northern US
522-2	3200R, Blue	32"	2008	Reverse	~19000	None	Pneumatic	Original	Now	180 day limited warranty (*)	\$34,000	Northern US
441-2	3300E, Blue	32"	2007	Standard	3359	None	Factory original	Original	Now	180 day limited warranty (*)	\$36,000	SE US
486-4	3300ER	32"	2006	Reverse	0 (new)	None	Factory Original	Original	Now	180 day limited warranty (*)	\$39,500	Southern CA
441-2	3300ER	32"	2011	Standard		None	Factory original	Original	Now	180 day limited warranty (*)	\$39,500	SE US
544-1	3600ER	36"	2007	Reverse		None	Factory original	Original	Now	180 day limited warranty (*)	\$39,500	NW US
541-1	3600, Blue (under contract)	36"	2013	See Note	<3000	Due 2023	Pneumatic	Original	Now	180 day limited warranty (*)	\$58,000	Detriot, MI
541-2	3600R, Blue (under contract)	36"	2013	See Note	<3000	Due 2023	Pneumatic	Original	Now	180 day limited warranty (*)	\$58,000	Detriot, MI
Note to AN-541: These chambers are a matched pair, one standard and one reverse. However, the info on which is which is not currently available.												
(*) Requires post del'y PM acceptable to HCI. If performed by HCI this is subject to separate pricing. International shipments are "as-is" at time of shipment. Warranties are normally parts only.												

General Notes to Sechrist Listings:

All chambers come with standard (non hydraulic) gurney unless inidcated otherwise, patient tray and mattress
 All chambers are built to PVHO-1, and all are National Board stamped excpet for some 2500 series chamber built in the early 1980s
 Maintenance records are available for most chambers
 All prices and techncial details subject to change without notice.

HYPERBAIRC CLEARINGHOUSE, INC.
www.hyperbaric-clearinghouse.com

POC: Stephen Reimers, P.E.
sreimers@hyperbaric-clearinghouse.com
ph: 703-863-3871

HCI Inventory of Pre-Owned Monoplace chamber Systems

HCI Inventory of Pre-Owned Monoplace chamber Systems

Perry- Chambers for sale

Latest Update: July 18, 2020 by SDR

Item Number	Model	Inside Diameter	Build Year	Control Panel Config.	Cycles	10 Year Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB
507-1	Sigma 40	40"	2008	Standard (left)	3,005	due	Pneumatic	Original	Now	180 day limited warranty (1)	\$59,500	SE US
507-2	Sigma 40	40"	2008	Reverse (Right)	2,705	due	Pneumatic	Original	Now	180 day limited warranty (1)	\$59,500	SE US
534-1	Sigma 36 (Under Contract)	36"	2012	Standard (left)	6,450	due in 2022	Pneumatic	Original	Call	180 day limited warranty (1)	\$51,500	PA
534-2	Sigma 36 (Under Contract)	36"	2012	Reverse (Right)	6,800	due in 2022	Pneumatic	Original	Call	180 day limited warranty (1)	\$51,500	PA
534-3	Sigma 36, White	36"	2015	Standard (left)	274	due in 2035	Pneumatic	Original	Call	180 day limited warranty (1)	\$59,000	SE US
534-4	Sigma 36, White	36"	2016	Reverse (Right)	306	due in 2036	Pneumatic	Original	Call	180 day limited warranty (1)	\$59,000	SE US
				Chamber Specific Notes:								
				1. Requires post del'y installation and PM by tech acceptable to HCI. Cost is \$2,400 per chamber if performed by HCI.								
				2. Requires post delivery set-up and check-out by Perry Technician. Cost is \$7,800 These chambers are best sold as a "matched pair".								

General Notes to Perry Listings:

All chambers come with standard (non hydraulic) gurney unless indicated otherwise, patient tray and mattress
 All chambers are built to PVHO-1 and are National Board stamped
 Maintenance records are available for most chambers
 All prices and technical details subject to change without notice.

HCI Inventory of Pre-Owned Monoplace chamber Systems

HYOX HTU2- Chambers for sale

Latest Update: July 17, 2020 by SDR

Item Number	Model	Inside Diameter	Build Year	Control Panel Config.	Cycles	10 Year Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB
510-1	HTU2 with RSI ODS-1 Hood & Mask Breathing System	N/A	1987	Standard See Photos	N/A	Due	Not applicable	New in 2007	Now	Refurbished & Upgraded to include new windows & Reimers Systems ODS-1 Oxygen Delivery System , Incl in 2007	Call	Lorton, VA
Maintenance support for these chambers is offered by Reimers Systems Division, PCCI, Inc., www.reimerssystems.com												
A standard annual PM normally runs about \$2,500 per chamber. A set of replacement windows installed at a PM is about a \$14,500 adder.												

General Notes to HTU2 Listings:

All chambers come with built-in patient chair that telescopes out for loading.
 Maintenance records are available for most chambers
 All prices and technical details subject to change without notice.